§ 35.700

(c) *Historic properties*. Section 35.115(a)(13) applies to this section.

Subpart H—Project-Based Rental Assistance

Source: 64 FR 50210, Sept. 15, 1999, unless otherwise noted.

§35.700 Purpose and applicability.

- (a) This subpart H establishes procedures to eliminate as far as practicable lead-based paint hazards in residential properties receiving project-based assistance under a HUD program. The requirements of this subpart apply only to the assisted dwelling units in a covered property and any common areas servicing those dwelling units. This subpart does not apply to housing receiving rehabilitation assistance or to public housing, which are covered by subparts J and M of this part, respectively.
- (b) For the purposes of competitively awarded grants under the Housing Opportunities for Persons with AIDS Program (HOPWA), the Supportive Housing Program (42 U.S.C. 11381-11389) and the Shelter Plus Care Program projectbased rental assistance and sponsorbased rental assistance components (42 U.S.C. 11402–11407), the requirements of this subpart shall apply to grants awarded pursuant to Notices of Funding Availability published on or after October 1, 1999. For the purposes of formula grants awarded under the Housing Opportunities for Persons with AIDS Program (HOPWA) (42 U.S.C. 12901 et seq.), the requirements of this subpart shall apply to activities for which program funds are first obligated on or after September 15, 2000.

§ 35.705 Definitions and other general requirements.

Definitions and other general requirements that apply to this subpart are found in subpart B of this part.

§35.710 Notices and pamphlet.

- (a) *Notice*. If evaluation or hazard reduction is undertaken, each owner shall provide a notice to occupants in accordance with §35.125.
- (b) Lead hazard information pamphlet. The owner shall provide the lead haz-

ard information pamphlet in accordance with §35.130.

\$35.715 Multifamily properties receiving more than \$5,000 per unit.

The requirements of this section shall apply to a multifamily residential property that is receiving an average of more than \$5,000 per assisted dwelling unit annually in project-based assistance.

- (a) Risk assessment. Each owner shall complete a risk assessment in accordance with §35.1320(b). A risk assessment is considered complete when the owner receives the risk assessment report. Until the owner conducts a risk assessment as required by this section, the requirements of paragraph (d) of this section shall apply. After the risk assessment has been conducted the requirements of paragraphs (b) and (c) of this section shall apply. Each risk assessment shall be completed no later than the following schedule or a schedule otherwise determined by HUD:
- (1) Risk assessments shall be completed on or before September 17, 2001, in a multifamily residential property constructed before 1960.
- (2) Risk assessments shall be completed on or before September 15, 2003, in a multifamily residential property constructed after 1959 and before 1978.
- (b) Interim controls. Each owner shall conduct interim controls in accordance with §35.1330 to treat the lead-based paint hazards identified in the risk assessment. Interim controls are considered completed when clearance is achieved in accordance with §35.1340. Interim controls shall be completed no later than the following schedule:
- (1) In units occupied by families with children of less than 6 years of age and in common areas servicing those units, interim controls shall be completed no later than 90 days after the completion of the risk assessment. In units in which a child of less than 6 years of age moves in after the completion of the risk assessment, interim controls shall be completed no later than 90 days after the move-in.
- (2) In all other dwelling units, common areas, and the remaining portions of the residential property, interim controls shall be completed no later